



October the 20<sup>th</sup> 21<sup>st</sup> & 22<sup>nd</sup> 1883  
 Surveyed in Section 18  
 T 7 R 4 W and  
 established corners  
 as per plat and field  
 notes below

A { 29 P. 19 $\frac{33}{38}$  lks east of the center of S 8  
 Red oak 10 S 44° E 23' lks  
 Gum 7 S 26 $\frac{1}{2}$ ° W 22 lks  
 Burr oak 2 S 21° W 3 $\frac{1}{2}$  lks

B { 26 Poles South of "A"  
 Elm 12 inches corner tree  
 marked with 4 notches

C { Center of N E  $\frac{1}{4}$  of S 8 or  
 Beech 20 S 70° W 66 lks  
 Beech 24 S 12° E 25 "

D { Half distance between E  $\frac{1}{2}$  on p & center  
 Black walnut 3 N 82 $\frac{1}{2}$ ° E 32 $\frac{3}{4}$  lks  
 Black walnut 3 N 12 $\frac{1}{2}$ ° W 28 "

E { 39 Poles 18 $\frac{3}{4}$  lks east of "D"  
 Black walnut 6 N 75° E 83 $\frac{1}{2}$  lks  
 Black walnut 5 N 78° E 54 $\frac{1}{2}$  "

F { 31 Poles 3 $\frac{1}{2}$  lks west of E  $\frac{1}{2}$  on p  
 Black walnut 7 S 32° E 10 lks  
 Elm 3 S 19° E 40 "

G { 48 $\frac{1}{2}$  Poles east of center  
 Red oak 2 S 35° W 22 $\frac{1}{4}$  lks H  
 Beech 12 S 57° E 81 "

This corner is 6 Poles east of its proper  
 place in order to get it out of the creek  
 Ash 5 N 32° W 6 Ash 18 S 28° W 8 $\frac{1}{2}$  lks

During the above survey the following persons  
 were sworn as Chairman Wm R Caffee  
 Andrew J Caffee, and Wilson Clark  
 Thomas B. Blackwell was sworn as flagman  
 The Survey was done by consent  
 of parties

I { 52 Poles South of "D"  
 Beech 24 N 86° W 15 $\frac{3}{4}$  lks  
 Beech 3 S 82° W 16 "

N H Baskirk.  
 M. L. S.